



Photo 1 – Duhamel Farm Partnership, 107 Franklin Rd., Highgate, VT – 08/03/16
Silage leachate collection system bay at the main farm.



Photo 2 – Duhamel Farm Partnership, 107 Franklin Rd., Highgate, VT – 08/03/16
Vegetated treatment area (VTA) and pond.



Photo 3 – Duhamel Farm Partnership, 107 Franklin Rd., Highgate, VT – 08/03/16

Leak from the low-flow tank transfer pipe.



Photo 4 – Duhamel Farm Partnership, 107 Franklin Rd., Highgate, VT – 08/03/16

Leachate leaking from a section of the silage bunker at the main farm.